



TECHNICAL BULLETIN

VANISH

Tarnish on silver, copper and brass is caused by oxidation and the presence of sulphur in the atmosphere. Some of the tarnish builds up over a period of time which is difficult and laborious to remove. VANISH is a product specially formulated to instantly remove all tarnish from silver, brass and copper. Care must be taken not to over soak items in the VANISH solution.

FEATURES

- Non toxic, can be handled by hands with no bad side effects.
- No dilution required, just pour and it is ready to use.
- Good bath life and also prolonged shelf life.
- No special storage required.

APPLICATION

VANISH is a mildly acidic product and care should be taken not to mix with chlorine agents or to store the liquid in metal containers for these will greatly reduce the solution strength.

Pour VANISH into a plastic bucket or container and dip items to be detarnished. Leave items for 1 - 2 minutes, remove, rinse thoroughly in cold water. Air dry and store.

For further information, consult Protek's representative.